

www.costvsvalue.com





### Midrange Project Descriptions

### ATTIC INSULATION (FIBERGLASS)

Air-seal a 35x30 attic floor to address any air leakage from conditioned spaced to unconditioned space. Then add fiberglass loosefill insulation, placing it on top of existing insulation if present. Fiberglass loosefill is applied until thickness equating with R-30 insulation value is reached.

### **BACKUP POWER GENERATOR**

Install modular propane gas-powered electrical backup system with capacity for providing 70 amps of emergency power in two 240-volt circuits and six 120-volt circuits. Assume existing propane gas supply. Include generator mounted on 2-by-4-foot concrete or composite pad, automatic transfer switch, load center, exterior disconnect, and grounding rod. Include 30 feet of conduit and electrical cable for generator connections; grounded cable for circuits; 5 feet of flexible fuel line for connection to existing rigid gas supply line; and automotive-type storage battery.

### **BACKYARD PATIO**

Install a 20x20 flagstone patio on flat ground behind the home. Connect the house and patio by installing a lift-and-slide glass door on the back of the house. Place a gas-powered fire pit in the center of the patio and surround it with four mid-priced all-weather deck chairs. On the far end of the patio from the home, install a stone-veneer modular kitchen unit with gas grill, mini-refrigerator, sink, and storage. From each corner of the patio, erect a 20x20 cedar pergola capable of holding an awning that can shade the entire deck. Install mid-priced, low-voltage lights on the pergola sufficient to illuminate the patio at night. Install all needed gas and electrical connections underground from the home to the patio.

### **BASEMENT REMODEL**

Finish the lower level of a house to create a 20-by-30-foot entertaining area with wet bar and a 5-by-8-foot full bathroom; construct 24 linear feet of finished partition to enclose mechanical area. Walls and ceilings are painted drywall throughout; exterior walls are insulated; painted trim throughout. Include five sixpanel factory-painted hardboard doors with passage locksets. Electrical wiring to code.

Main room: Include 15 recessed ceiling light fixtures and three surface-mounted light fixtures, and a snap-together laminate flooring system.

Bathroom: Include standard white toilet, vanity with cultured marble top, resilient vinyl flooring, two-piece fiberglass shower unit, a light/fan combination, vanity light fixture, recessed medicine cabinet, towel and paper-holder hardware.

Bar area: Include 10 linear feet of raised-panel oak cabinets with laminate countertops, stainless steel bar sink, single-lever bar faucet, undercounter refrigerator, and vinyl floor tile.

### **BATHROOM ADDITION**

Add a full 6-by-8-foot bathroom over a crawlspace with poured concrete walls. Include cultured-marble vanity top with molded sink; standard chrome faucets; 30-by-60-inch white fiberglass tub/ shower with ceramic tile surround; single-lever temperature and pressure-balanced faucet; white low-profile toilet; general and spot lighting; electrical wiring to code; mirrored medicine cabinet; linen storage closet or cabinet; vinyl wallpaper; painted trim; and ceramic tile floor.

### **BATHROOM REMODEL**

Update an existing 5-by-7-foot bathroom. Replace all fixtures to include 30-by-60-inch porcelain-on-steel tub with 4-by-4-inch ceramic tile surround; new single-lever temperature and pressure-balanced shower control; standard white toilet; solid-surface vanity counter with integral sink; recessed medicine cabinet with light; ceramic tile floor; vinyl wallpaper.

### **DECK ADDITION (COMPOSITE)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. Install composite deck material in a simple linear pattern. Include a built-in bench and planter of the same decking material. Include stairs, assuming three steps to grade. Provide a complete railing using a matching system made of the same composite as the decking material.

### **DECK ADDITION (WOOD)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. Install pressure-treated deck boards in a simple linear pattern. Include a built-in bench and planter of the same decking material. Include stairs, assuming three steps to grade. Provide a complete railing system using pressure-treated wood posts, railings, and balusters.

### **ENTRY DOOR REPLACEMENT (FIBERGLASS)**

Remove existing 3-0/6-8 entry door and jambs and replace with fiberglass door with simulated wood grain, stained same color both sides; dual-pane, decorative half-glass panel with zinc caming; PVC-wrapped exterior trim in color to match existing trim; 2.5-inch interior colonial or ranch casings in hardwood stained to match door. Replace existing lockset with mortise lock with lever handle and integrated deadbolt.

### **ENTRY DOOR REPLACEMENT (STEEL)**

Remove existing 3-0/6-8 entry door and jambs and replace with new 20-gauge steel unit, including clear dual-pane half-glass panel, jambs, and aluminum threshold with composite stop. Door is factory finished with same color both sides. Exterior brick-mold and 2.5-inch interior colonial or ranch casings in poplar or equal prefinished to match door color. Replace existing lockset with new bored-lock.



### **FAMILY ROOM ADDITION**

In a style appropriate to the existing house, add a 16-by-25-foot room on a crawlspace foundation with siding and fiberglass shingle roof. Include drywall interior with fiberglass insulation, pre-finished hardwood floor, and 180 square feet of glazing including windows, atrium-style exterior doors, and two operable skylights. Tie into existing HVAC. Add electrical system to code, including 12 recessed ceiling lights.

### **GARAGE DOOR REPLACEMENT**

Remove and dispose of existing 16x7-foot garage door and tracks. Install new 4-section garage door on new galvanized steel tracks; reuse existing motorized opener. New door is uninsulated, single-layer, embossed steel with two coats of baked-on paint, galvanized steel hinges, and nylon rollers. 10-year limited warranty.

### **MAJOR KITCHEN REMODEL**

Update an outmoded 200-square-foot kitchen with a functional layout of 30 linear feet of semi-custom wood cabinets, including a 3-by-5-foot island; laminate countertops; and standard double-tub stainless-steel sink with standard single-lever faucet. Include energy-efficient range, ventilation system, built-in microwave, dishwasher, garbage disposal, and custom lighting. Add new resilient flooring. Finish with painted walls, trim, and ceiling.

### **MANUFACTURED STONE VENEER**

Remove a 300 square-foot continuous band of existing vinyl siding from the bottom third of the street-facing façade, beginning at the garage, continuing around the main entry, and ending at the corner of the side addition. Replace with adhered manufactured stone veneer, including 36 linear feet (LF) of sills, 40 LF of corners, and one address block. Installation includes two separate layers of water resistive barrier laid over bare sheathing, corrosion resistant lath and fasteners, and nominal ½-inch-thick mortar scratch coat and setting bed. Outline the archway using an 8x10-inch keystone and a soldier course of flats on either side.

### **MASTER SUITE ADDITION**

Add a 24-by-16-foot master bedroom suite over a crawlspace. Include walk-in closet/dressing area, a freestanding soaker tub, separate 3-by-4-foot ceramic tile shower, and double-bowl vanity with solid-surface countertop. Bedroom floor is carpet; bathroom floor is ceramic tile. Painted walls, ceiling, and trim. General and spot lighting, exhaust fan; electrical wiring to code.

### MINOR KITCHEN REMODEL

In a functional but dated 200-square-foot kitchen with 30 linear feet of cabinetry and countertops, leave cabinet boxes in place but replace fronts with new shaker-style wood panels and drawer fronts, including new hardware. Replace cooktop/oven range and slide-in refrigerator with new energy-efficient models. Replace

laminate countertops; install midpriced sink and faucet. Repaint trim, add wall covering, and remove and replace resilient flooring.

### **ROOFING REPLACEMENT**

Remove existing roofing to bare wood sheathing and dispose of properly. Install 30 squares of 235-pound fiberglass asphalt shingles (min. 25-year warranty) with new felt underlayment, galvanized drip edge, and mill-finish aluminum flashing. Assume a 5-square hip roof; custom flashing at two average-size skylights; and custom cap treatment at vented ridge.

### SIDING REPLACEMENT

Replace 1,250 square feet of existing siding with new siding. Include factory trim at all openings and corners.

### **TWO-STORY ADDITION**

In a style similar to the rest of the home, add a first-floor family room and a second-floor bedroom with full bathroom in a 24-by-16-foot two-story wing over a crawlspace. Add new HVAC system to handle addition; electrical wiring to code.

Family room: Include a prefabricated gas fireplace; 11 3-by-5-foot double-hung insulated clad-wood windows; an atrium-style exterior door; carpeted floors; painted drywall on walls and ceiling; and painted trim.

Bathroom: 5 by 8 feet. Include a one-piece fiberglass tub/shower unit; standard white toilet; wood vanity with solid-surface countertop; resilient vinyl flooring; and mirrored medicine cabinet with built-in light strip; papered walls; and painted trim; exhaust fan.

Bedroom: Include walk-in closet/dressing area; carpet; painted walls, ceiling, and trim; general and spot lighting.

### **UNIVERSAL DESIGN BATHROOM**

Begin with an existing 5x7 bathroom with toilet, tub shower, storage space, overhead light, tile floor, and single bathroom vanity with sink and a mirror behind the sink. Widen doorway so the room is accessible by wheelchair. Replace existing door with a wood interior door and standard interior door knobs with pushbutton lock. Reinforce bathroom walls as appropriate to support grab bars, towel hooks, and seats. Place electrical switches and outlets at heights that make them accessible to a person in a wheelchair. Replace existing 3x5 tub/shower unit with a walk-in, zero-threshold shower. Install a fold-down seat in the shower area. Use a height-adjustable/removable shower head. Replace existing toilet with comfort-height toilet. Install support bars as needed next to the toilet. Replace the bathroom vanity and sink with a unit whose doors are easily accessible while sitting and has space beneath for a person to sit comfortably at it. Install a standard porcelain sink and faucets with lever handles. Place mid-priced light fixtures on either side of the mirror. Replace overhead lighting with a 100-watt equivalent LED unit. Reconfigure storage so it can be accessed from a wheelchair.



### **Upscale Project Descriptions**

### **BATHROOM ADDITION**

Add a new 100-square-foot master bathroom to existing master bedroom over a crawlspace. Include 42-by-42-inch neo-angle shower with ceramic tile walls with accent strip, recessed shower caddy, body-spray fixtures, and frameless glass enclosure. Include a freestanding soaker tub with high-end faucets; stone countertop with two sinks; two mirrored medicine cabinets with lighting; a compartmentalized commode area with one-piece toilet; and a humidistat-controlled exhaust fan. Use all color fixtures. Use larger matching ceramic tiles on the floor, laid on the diagonal with ceramic tile base molding. Add general and spot lighting including waterproof shower fixture. Cabinetry shall include a custom drawer base and wall cabinets for a built-in look. Extend HVAC system, and include electric in-floor heating.

### **BATHROOM REMODEL**

Expand an existing 35-square-foot bathroom to 100 square feet within existing house footprint. Relocate all fixtures. Include 42-by-42-inch neo-angle shower with ceramic tile walls with accent strip, recessed shower caddy, body-spray fixtures, and frameless glass enclosure. Include a freestanding soaker tub with high-end faucets; stone countertop with two sinks; two mirrored medicine cabinets with lighting; a compartmentalized commode area with one-piece toilet; and a humidistat-controlled exhaust fan. Use all color fixtures. Use larger matching ceramic tiles on the floor, laid on the diagonal with ceramic tile base molding. Add general and spot lighting including waterproof shower fixture. Cabinetry shall include a custom drawer base and wall cabinets for a built-in look. Extend HVAC system, and include electric in-floor heating.

### **DECK ADDITION (COMPOSITE)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. At one corner, add a second, 10-foot-diameter six-sided platform one step down from the main deck. Include stairs on the smaller deck, assuming three steps to grade. Install composite deck material in a simple linear pattern. Trim the perimeter joists and wrap the 4x4 posts with composite materials to match the decking. Using the same decking material, include a built-in bench and planter along one 16-foot side. On the remaining perimeter, provide a railing system using composite material of contrasting or complementary colors that includes decorative balusters, post caps, and lighting. Railing and trim should provide for overall curb appeal to the outdoor living space by integrating the deck with the home's color and architecture, creating a custom look.

### **GARAGE DOOR REPLACEMENT**

Remove and dispose of existing 16x7-foot garage door and tracks. Install new 4-section garage door on new heavy-duty galvanized steel tracks; reuse existing motorized opener. New door is high-tensilestrength steel with two coats of factory-applied paint, and foam insulated to minimum R-12, with thermal seals between pinch-resistant panels. Windows in top panel are ½-inch insulated

glass. Hardware includes galvanized steel hinges and ball-bearing urethane rollers. Lifetime warranty.

### **GRAND ENTRANCE (FIBERGLASS)**

Remove existing 3-0/6-8 entry door and cut and reframe opening for a 12-36-12 entrance door with dual sidelites. Move double-gang electrical box with two switches. Fiberglass door blank matches upscale entry, including color, threshold, lockset, and decorative half-glass; sidelites match door. PVC-wrapped exterior trim in color to match existing trim; wider interior colonial or ranch casings (3.5-inch to cover new jack studs) in hardwood stained to match door. All work to be completed in one day.

### **MAJOR KITCHEN REMODEL**

Update outmoded 200-square-foot kitchen with 30 linear feet of top-of-the-line custom white cabinets with built-in sliding shelves and other interior accessories. Include stone countertops with imported ceramic- or glass-tile backsplash; built-in refrigerator, commercial grade cooktop and vent hood, wall oven, and built-in microwave unit. Install high-end undermount sink with designer faucets and water filtration system. Add new general and task lighting, including low-voltage undercabinet lights. Install tile or similar flooring that looks like wood.

### **MASTER SUITE ADDITION**

Add a 32-by-20-foot master bedroom suite over a crawlspace.

Bedroom: Add a spacious sleeping area with lounging/sitting area adjacent to large master bathroom. Include custom bookcases and built-in storage with millwork details; high-end gas fireplace with stone hearth and custom mantle; and large walk-in closet/dressing area with natural light, mirrors, and linen storage. Add French doors to exterior.

Bathroom: Include a large walk-in shower with dual-shower system, stone shower walls and floor, and custom frameless glass enclosure. Add freestanding soaker tub. Include two sinks in separate custom vanities with stone countertops and large mirrors. Create partitioned area for luxury one-piece toilet.

General: Add 5-foot-long hospitality center with bar sink, undercounter refrigerator, custom cabinetry, granite or marble countertop, and microwave. Include soundproofing, in-floor heating, custom wall finishes and hardware, general and spot lighting, and lighting controls.

### WINDOW REPLACEMENT (VINYL)

Replace 10 existing 3-by-5-foot double-hung windows with insulated, low-E, simulated-divided-lite vinyl windows. Simulated wood-grain interior finish; custom-color exterior finish. Trim exterior to match existing; do not disturb existing interior trim.

### WINDOW REPLACEMENT (WOOD)

Replace 10 existing 3-by-5-foot double-hung windows with insulated, low-E, simulated-divided-lite wood windows. Interior finish of stained hardwood; exterior finish of custom-color aluminum cladding. Trim exterior to match existing; do not disturb existing interior trim.



### Reuse and Licensing of Data

### COPYRIGHTED MATERIAL

The Remodeling Cost vs. Value Report contains copyrighted material that is being made available in free downloadable PDF documents as a public service. Any reuse without express permission is prohibited, including but not limited to the following:

- 1. RESALE. The Cost vs. Value Report, whether in whole or part, may not be reproduced and sold in any format, including print, digital, electronic file, fax, or other medium.
- 2. PUBLICATION OF DATA. The Cost vs. Value Report, whether in whole or part, may not be distributed or published in any format, including print, digital, electronic file, fax, or other medium without obtaining express permission.
- 3. APPLICATIONS/SOFTWARE. The Cost vs. Value Report, whether in whole or part, may not be incorporated for use in any kind of computer- or Web-based application, calculator, database, or other automated, electronic, or digital device, instrument, or software except as licensed by Hanley Wood (see Licensing, below).

### **EXCERPTING COST VS. VALUE REPORT DATA**

Excerpts of Cost vs. Value Report data may not take the form of a chart or table that simulates the manner in which the data is displayed at www.costvsvalue.com.

Excerpts of Cost vs. Value Report data may, however, be made as part of a narrative, provided that the sum total of all excerpts from any publisher in all formats does not exceed data from more than five projects.

### **ACKNOWLEDGING COST VS. VALUE AS DATA SOURCE**

When excerpting Cost vs. Value Report data, refer to the "Remodeling 2016 Cost vs. Value Report" and include the URL www.costvsvalue.com, as in the following examples:

- "... according to the Remodeling 2017 Cost vs. Value Report (www.costvsvalue.com) ..."
- "... as compiled in the Remodeling 2017 Cost vs. Value Report

(www.costvsvalue.com) ...."

This form of citation should be used in the first instance on every page of a multipage online story that cites the Cost vs. Value Report on multiple pages. Subsequent references on a given page may be foreshortened to "Cost vs. Value Report."

All excerpts must be accompanied by one or more instances of the following acknowledgements of copyright:

"© 2017 Hanley Wood Media Inc. Complete data from the Remodeling

2017 Cost vs. Value Report can be downloaded free at www.costvsvalue.com."

### LICENSING OF 2017 COST VS. VALUE REPORT DATA

For permission to license data from the 2017 Cost vs. Value Report for use in any kind of computer- or Web-based application, calculator, database, or other automated, electronic, or digital device, instrument, or software, include the following in an email request to **costvsvaluepermissions@hanleywood.com** 

- a description of the application, calculator, or device for which use of the data is being requested. Include the length of time for which the license is sought.
- a detailed description of the material to be licensed (e.g., specific projects, cities, etc.).



PROJECT TYPE	CHICAGO			
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,410	\$1,248	88.5%	
Backup Power Generator	14,615	6,189	42.3%	
Backyard Patio	63,891	29,621	46.4%	
Basement Remodel	88,281	45,868	52.0%	
Bathroom Addition	52,737	28,507	54.1%	
Bathroom Remodel	23,458	14,243	60.7%	
Deck Addition (composite)	19,680	12,316	62.6%	
Deck Addition (wood)	13,663	8,457	61.9%	
Entry Door Replacement (fiberglass)	3,437	2,670	77.7%	
Entry Door Replacement (steel)	1,522	1,589	104.4%	
Family Room Addition	110,765	70,743	63.9%	
Garage Door Replacement	2,094	1,791	85.5%	
Major Kitchen Remodel	72,297	43,597	60.3%	
Manufactured Stone Veneer	7,940	8,300	104.5%	
Master Suite Addition	140,865	83,254	59.1%	
Minor Kitchen Remodel	25,126	18,945	75.4%	
Roofing Replacement	26,684	15,544	58.3%	
Siding Replacement	17,901	12,748	71.2%	
Two-Story Addition	202,664	141,040	69.6%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 21,313	\$ 12,835	60.2%	
Bathroom Addition	94,953	51,243	54.0%	
Bathroom Remodel	68,235	39,102	57.3%	
Deck Addition (composite)	45,824	23,607	51.5%	
Garage Door Replacement	3,403	2,426	71.3%	
Grand Entrance (fiberglass)	8,678	6,124	70.6%	
Major Kitchen Remodel	138,922	80,790	58.2%	
Master Suite Addition	282,498	150,970	53.4%	
Window Replacement (vinyl)	17,096	12,118	70.9%	
Window Replacement (wood)	20,309	13,934	68.6%	

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



PROJECT TYPE	EAST NORTH CENTRAL			
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,351	\$1,071	79.3%	
Backup Power Generator	13,055	5,835	44.7%	
Backyard Patio	53,518	25,080	46.9%	
Basement Remodel	72,856	38,828	53.3%	
Bathroom Addition	44,578	20,076	45.0%	
Bathroom Remodel	19,285	10,994	57.0%	
Deck Addition (composite)	17,393	9,142	52.6%	
Deck Addition (wood)	10,864	6,147	56.6%	
Entry Door Replacement (fiberglass)	3,286	2,439	74.2%	
Entry Door Replacement (steel)	1,425	1,103	77.4%	
Family Room Addition	92,075	54,573	59.3%	
Garage Door Replacement	1,792	1,187	66.2%	
Major Kitchen Remodel	63,282	34,125	53.9%	
Manufactured Stone Veneer	7,853	6,166	78.5%	
Master Suite Addition	121,780	72,212	59.3%	
Minor Kitchen Remodel	21,303	15,348	72.0%	
Roofing Replacement	20,859	12,874	61.7%	
Siding Replacement	14,788	9,662	65.3%	
Two-Story Addition	177,167	108,758	61.4%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 16,440	\$ 9,060	55.1%	
Bathroom Addition	83,101	40,511	48.7%	
Bathroom Remodel	61,196	30,229	49.4%	
Deck Addition (composite)	39,993	16,735	41.8%	
Garage Door Replacement	3,301	2,239	67.8%	
Grand Entrance (fiberglass)	8,364	5,029	60.1%	
Major Kitchen Remodel	125,164	75,395	60.2%	
Master Suite Addition	253,908	123,921	48.8%	
Window Replacement (vinyl)	15,406	9,634	62.5%	
Window Replacement (wood)	18,920	11,832	62.5%	

CONFIDENCE LEVEL: 95% +/-6.9

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.




PROJECT TYPE	2017			
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,343	\$1,446	107.7%	
Backup Power Generator	12,860	6,940	54.0%	
Backyard Patio	51,985	28,546	54.9%	
Basement Remodel	71,115	49,768	70.0%	
Bathroom Addition	43,232	23,283	53.9%	
Bathroom Remodel	18,546	12,024	64.8%	
Deck Addition (composite)	17,249	11,252	65.2%	
Deck Addition (wood)	10,707	7,652	71.5%	
Entry Door Replacement (fiberglass)	3,276	2,550	77.8%	
Entry Door Replacement (steel)	1,413	1,282	90.7%	
Family Room Addition	89,566	62,055	69.3%	
Garage Door Replacement	1,749	1,345	76.9%	
Major Kitchen Remodel	62,158	40,560	65.3%	
Manufactured Stone Veneer	7,851	7,019	89.4%	
Master Suite Addition	119,533	77,506	64.8%	
Minor Kitchen Remodel	20,830	16,699	80.2%	
Roofing Replacement	20,664	14,214	68.8%	
Siding Replacement	14,518	11,093	76.4%	
Two-Story Addition	176,108	125,222	71.1%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 15,730	\$ 10,766	68.4%	
Bathroom Addition	81,515	46,507	57.1%	
Bathroom Remodel	59,979	35,456	59.1%	
Deck Addition (composite)	39,339	22,171	56.4%	
Garage Door Replacement	3,304	2,810	85.0%	
Grand Entrance (fiberglass)	8,358	5,855	70.1%	
Major Kitchen Remodel	122,991	76,149	61.9%	
Master Suite Addition	250,687	150,140	59.9%	
Window Replacement (vinyl)	15,282	11,286	73.9%	
Window Replacement (wood)	18,759	13,691	73.0%	

CONFIDENCE LEVEL: 95% +/-2.6

Note: In four markets—Pensacola, Palm Springs, Quad Cities, and West Palm Beach—the job costs are an average of the costs for that project in that particular market's Census Division.

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



Chicago, IL

hanley

MIDRANGE	PROJECT TYPE		CHICAGO		EA	EAST NORTH CENTRAL			2017 NATIONAL AVERAG		
Backup Power Generator	MIDRANGE									Cost Recouped	
Backyard Patio         63,891         29,621         46,4%         53,518         25,080         46,9%         51,985         28,546           Basement Remodel         88,281         45,688         52,0%         72,856         38,828         53,3%         71,115         49,768           Bathroom Addition         52,737         28,507         54,1%         44,578         20,076         45,0%         43,232         23,283           Bathroom Remodel         23,458         14,243         60.7%         19,285         10,994         57,0%         18,546         12,024           Deck Addition (composite)         19,680         12,316         62,6%         17,393         9,142         52,6%         17,249         11,252           Deck Addition (composite)         13,663         8,457         61.9%         10,864         6,147         56,6%         10,707         7,652           Entry Door Replacement (steel)         1,522         1,589         104.4%         1,425         1,03         77.4%         1,439         74.2%         3,276         2,550           Entry Door Replacement (steel)         1,522         1,589         104.4%         1,425         1,03         77.4%         1,439         74.2%         3,276	Attic Insulation (fiberglass)	\$1,410	\$1,248	88.5%	\$1,351	1 \$1,071	79.3%	\$1,343	\$1,446	107.7%	
Basement Remodel	Backup Power Generator	14,615	6,189	42.3%	13,05	5 5,835	44.7%	12,860	6,940	54.0%	
Bathroom Addition         52,737         28,507         54,1%         44,578         20,076         45,0%         43,232         23,283           Bathroom Remodel         23,458         14,243         60,7%         19,285         10,994         57,0%         18,546         12,024           Deck Addition (composite)         19,868         12,316         62,6%         17,333         9,142         52,6%         17,249         11,252           Deck Addition (wood)         13,663         8,457         61.9%         10,864         6,147         56,6%         10,707         7,652           Entry Door Replacement (fiberglass)         3,437         2,670         77,7%         3,286         2,439         74,2%         3,276         2,550           Entry Door Replacement (steel)         1,522         1,588         104,4%         1,425         1,103         77,7%         4,1413         1,282           Family Room Addition         110,765         70,743         63,9%         92,075         54,573         59,3%         89,566         62,055           Garage Door Replacement         2,094         1,791         85,5%         1,792         1,187         66,2%         1,749         1,345           Major Kitchen Remodel         7	Backyard Patio	63,891	29,621	46.4%	53,518	3 25,080	46.9%	51,985	28,546	54.9%	
Bathroom Remodel         23,458         14,243         60.7%         19,285         10,994         57.0%         18,546         12,024           Deck Addition (composite)         19,680         12,316         62.6%         17,393         9,142         52.6%         17,249         11,252           Deck Addition (wood)         13,663         8,457         61.9%         10,864         6,147         56.6%         10,707         7,652           Entry Door Replacement (tiberglass)         3,437         2,670         77.7%         3,286         2,439         74.2%         3,276         2,550           Entry Door Replacement (tiberglass)         1,522         1,589         104.4%         1,425         1,103         77.4%         1,413         1,282           Family Room Addition         110,765         70,743         63.9%         92,075         54,573         59.3%         89,566         62,055           Garage Door Replacement         2,094         1,791         85.5%         1,792         1,187         66.2%         1,749         1,345           Major Kitchen Remodel         72,297         43,597         60.3%         63,282         34,125         53.9%         62,158         40,560           Manufactured Stone Veneer	Basement Remodel	88,281	45,868	52.0%	72,856	38,828	53.3%	71,115	49,768	70.0%	
Deck Addition (composite)   19,680   12,316   62.6%   17,393   9,142   52.6%   17,249   11,252	Bathroom Addition	52,737	28,507	54.1%	44,578	3 20,076	45.0%	43,232	23,283	53.9%	
Deck Addition (wood)	Bathroom Remodel	23,458	14,243	60.7%	19,28	5 10,994	57.0%	18,546	12,024	64.8%	
Entry Door Replacement (fiberglass) Entry Door Replacement (steel) 1,522 1,589 104.4% 1,425 1,103 77.4% 1,413 1,282 Family Room Addition 110,765 70,743 63.9% 92,075 54,573 59.3% 89,566 62,055 Garage Door Replacement 2,094 1,791 85.5% 1,792 1,187 66.2% 1,749 1,345 Major Kitchen Remodel 72,297 43,597 60.3% 63,282 34,125 53.9% 62,158 40,560 Manufactured Stone Veneer 7,940 8,300 104.5% 7,853 6,166 78.5% 7,851 7,019 Master Suite Addition 140,865 83,254 59.1% 121,780 72,212 59.3% 119,533 77,506 Minor Kitchen Remodel 25,126 18,945 75,4% 21,303 15,348 72.0% 20,830 16,699 Roofing Replacement 26,684 15,544 58.3% 20,859 12,874 61.7% 20,664 142,14 Siding Replacement 17,901 12,748 71,2% 14,788 9,662 65.3% 14,518 11,093 Two-Story Addition 94,953 51,243 54.0% 83,101 40,511 48.7% 81,515 46,507 Bathroom Remodel 68,235 39,102 57.3% 61,196 30,229 49,4% 59,979 35,456 Deck Addition (composite) 45,824 23,607 51.5% 39,993 16,735 41.8% 39,339 22,171 Garage Door Replacement 3,403 2,426 71,3% 3,301 2,239 60.2% 14,888 60.2% 14,889 60.2% 14,889 60.29 60.1% 8,358 5,855 Major Kitchen Remodel 138,922 80,790 58.2% 125,164 75,395 60.2% 18,980 18,759 13,691  Window Replacement (vinyl) 17,096 12,118 70,9% 11,832 62.5% 18,759 13,691	Deck Addition (composite)	19,680	12,316	62.6%	17,393	3 9,142	52.6%	17,249	11,252	65.2%	
Entry Door Replacement (steel) 1,522 1,589 104.4% 1,425 1,103 77.4% 1,413 1,282 Family Room Addition 110,765 70,743 63.9% 92,075 54,573 59.3% 89,566 62,055 Garage Door Replacement 2,094 1,791 85.5% 1,792 1,187 66.2% 1,749 1,345 Major Kitchen Remodel 72,297 43,597 60.3% 63,282 34,125 53.9% 62,158 40,560 Manufactured Stone Veneer 7,940 8,300 104.5% 7,853 6,166 78.5% 7,851 7,019 Master Suite Addition 140,865 83,254 59.1% 121,780 72,212 59.3% 119,533 77,506 Minor Kitchen Remodel 25,126 18,945 75.4% 21,303 15,348 72.0% 20,830 16,699 Roofing Replacement 26,664 15,544 58.3% 20,859 12,874 61.7% 20,664 14,214 Siding Replacement 17,901 12,748 71.2% 14,788 9,662 65.3% 14,518 11,093 Two-Story Addition 202,664 141,040 69.6% 177,167 108,758 61.4% 176,108 125,222  UPSCALE  Universal Design Bathroom \$21,313 \$12,835 60.2% \$16,440 \$9,060 \$5.1% \$15,730 \$10,766 Bathroom Addition 94,953 51,243 54.0% 83,101 40,511 48.7% 81,515 46,507 Bathroom Remodel 68,235 39,102 57.3% 61,196 30,229 49.4% 59,979 35,456 Deck Addition (composite) 45,824 23,607 51.5% 39,993 16,735 41.8% 39,339 22,171 Garage Door Replacement 3,403 2,426 71,3% 3,001 2,239 67.8% 3,304 2,810 Grand Entrance (fiberglass) 8,678 6,124 70.6% 8,364 5,029 60.1% 8,358 5,855 Major Kitchen Remodel 138,922 80,790 58.2% 125,164 75,395 60.2% 12,991 76,149 Master Suite Addition 282,498 150,970 53.4% 253,908 123,921 48.8% 250,687 150,140 Window Replacement (wood) 20,309 13,934 68.6% 18,920 11,832 62.5% 18,759 13,691	Deck Addition (wood)	13,663	8,457	61.9%	10,864	4 6,147	56.6%	10,707	7,652	71.5%	
Family Room Addition	Entry Door Replacement (fiberglass)	3,437	2,670	77.7%	3,286	5 2,439	74.2%	3,276	2,550	77.8%	
Garage Door Replacement         2,094         1,791         85.5%         1,792         1,187         66.2%         1,749         1,345           Major Kitchen Remodel         72,297         43,597         60.3%         63,282         34,125         53.9%         62,158         40,560           Manufactured Stone Veneer         7,940         8,300         104.5%         7,853         6,166         78.5%         7,851         7,019           Master Suite Addition         140,865         83,254         59.1%         121,780         72,212         59.3%         119,533         77,506           Minor Kitchen Remodel         25,126         18,945         75.4%         21,303         15,348         72.0%         20,830         16,699           Roofing Replacement         26,684         15,544         58.3%         20,859         12,874         61.7%         20,664         14,214           Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           Upscale         Cost <td>Entry Door Replacement (steel)</td> <td>1,522</td> <td>1,589</td> <td>104.4%</td> <td>1,42</td> <td>5 1,103</td> <td>77.4%</td> <td>1,413</td> <td>1,282</td> <td>90.7%</td>	Entry Door Replacement (steel)	1,522	1,589	104.4%	1,42	5 1,103	77.4%	1,413	1,282	90.7%	
Major Kitchen Remodel         72,297         43,597         60.3%         63,282         34,125         53.9%         62,158         40,560           Manufactured Stone Veneer         7,940         8,300         104.5%         7,853         6,166         78.5%         7,851         7,019           Master Suite Addition         140,865         83,254         59.1%         121,780         72,212         59.3%         119,533         77,506           Minor Kitchen Remodel         25,126         18,945         75.4%         21,303         15,348         72.0%         20,830         16,699           Roofing Replacement         26,684         15,544         58.3%         20,859         12,874         61.7%         20,664         14,214           Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           UPSCALE         Job Resale Cost Value         Cost Value         Recouped         Cost Value         Recouped         Cost Value         Recouped         Cost Value         176,108         <	Family Room Addition	110,765	70,743	63.9%	92,075	5 54,573	59.3%	89,566	62,055	69.3%	
Manufactured Stone Veneer         7,940         8,300         104.5%         7,853         6,166         78.5%         7,851         7,019           Master Suite Addition         140,865         83,254         59.1%         121,780         72,212         59.3%         119,533         77,506           Minor Kitchen Remodel         25,126         18,945         75.4%         21,303         15,348         72.0%         20,830         16,699           Roofing Replacement         26,684         15,544         58.3%         20,859         12,874         61.7%         20,664         14,214           Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           UPSCALE         Job Cost Value         Resale Recouped         Cost Value         Recouped         Cost Value         Recouped         Cost Cost Cost Value	Garage Door Replacement	2,094	1,791	85.5%	1,792	2 1,187	66.2%	1,749	1,345	76.9%	
Master Suite Addition         140,865         83,254         59.1%         121,780         72,212         59.3%         119,533         77,506           Minor Kitchen Remodel         25,126         18,945         75.4%         21,303         15,348         72.0%         20,830         16,699           Roofing Replacement         26,684         15,544         58.3%         20,859         12,874         61.7%         20,664         14,214           Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           UPSCALE         Job Cost Value         Resale Recouped         Cost Value         Recouped         Cost Value         Recouped         Cost Value         176,108         125,222           Universal Design Bathroom         \$21,313         \$12,835         60.2%         \$16,440         \$9,060         55.1%         \$15,730         \$10,766           Bathroom Addition         94,953         51,243         54.0%         83,101         40,511         48.7%         81,515         46,507	Major Kitchen Remodel	72,297	43,597	60.3%	63,282	2 34,125	53.9%	62,158	40,560	65.3%	
Minor Kitchen Remodel         25,126         18,945         75.4%         21,303         15,348         72.0%         20,830         16,699           Roofing Replacement         26,684         15,544         58.3%         20,859         12,874         61.7%         20,664         14,214           Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           UPSCALE         Job Cost Value         Resale Cost Value         Lost Value         Lost Value         Recouped Cost Value         Lost Value         Lost Value         Recouped Cost Value         Lost Val	Manufactured Stone Veneer	7,940	8,300	104.5%	7,853	3 6,166	78.5%	7,851	7,019	89.4%	
Roofing Replacement   26,684   15,544   58.3%   20,859   12,874   61.7%   20,664   14,214	Master Suite Addition	140,865	83,254	59.1%	121,780	72,212	59.3%	119,533	77,506	64.8%	
Siding Replacement         17,901         12,748         71.2%         14,788         9,662         65.3%         14,518         11,093           Two-Story Addition         202,664         141,040         69.6%         177,167         108,758         61.4%         176,108         125,222           UPSCALE         Job Cost         Resale Value         Cost         Value         Recouped         Cost         Value           Universal Design Bathroom         \$21,313         \$12,835         60.2%         \$16,440         \$9,060         55.1%         \$15,730         \$10,766           Bathroom Addition         94,953         51,243         54.0%         83,101         40,511         48.7%         81,515         46,507           Bathroom Remodel         68,235         39,102         57.3%         61,196         30,229         49.4%         59,979         35,456           Deck Addition (composite)         45,824         23,607         51.5%         39,993         16,735         41.8%         39,339         22,171           Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678	Minor Kitchen Remodel	25,126	18,945	75.4%	21,303	3 15,348	72.0%	20,830	16,699	80.2%	
UPSCALE         Job Cost         Resale Value         Cost Value         Job Cost         Resale Value         Cost Value         Job Cost Value         Resale Recouped         Cost Value         Job Cost Value         Resole Recouped         Cost Value         Job Cost Value         Nation Incomes Value         Job Cost Value         Massile Value         Job Cost Value         Job Cost Value         Massile Value         Massile Value         Job Cost Value         Massile Value         Massile Value         Job Cost Value         Massile Value         Massile Value         Job Cost Value         Massile Value         Job Cost Value         Massile Value         Job Cost Value         J	Roofing Replacement	26,684	15,544	58.3%	20,859	9 12,874	61.7%	20,664	14,214	68.8%	
UPSCALE         Job Cost         Resale Value         Cost Value         Job Cost         Resale Recouped         Cost Value         Value Recouped         Cost Value         Job Resale Recouped         Cost Value         Value         Recouped         Cost Value         Value         Resale Cost Value         Val	Siding Replacement	17,901	12,748	71.2%	14,788	9,662	65.3%	14,518	11,093	76.4%	
UPSCALE         Cost         Value         Recouped         Cost         Value         Recouped         Cost         Value           Universal Design Bathroom         \$21,313         \$12,835         60.2%         \$16,440         \$9,060         55.1%         \$15,730         \$10,766           Bathroom Addition         94,953         51,243         54.0%         83,101         40,511         48.7%         81,515         46,507           Bathroom Remodel         68,235         39,102         57.3%         61,196         30,229         49.4%         59,979         35,456           Deck Addition (composite)         45,824         23,607         51.5%         39,993         16,735         41.8%         39,339         22,171           Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498	Two-Story Addition	202,664	141,040	69.6%	177,167	7 108,758	61.4%	176,108	125,222	71.1%	
Bathroom Addition         94,953         51,243         54.0%         83,101         40,511         48.7%         81,515         46,507           Bathroom Remodel         68,235         39,102         57.3%         61,196         30,229         49.4%         59,979         35,456           Deck Addition (composite)         45,824         23,607         51.5%         39,993         16,735         41.8%         39,339         22,171           Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         18,759         13,691		Cost	Value	Recouped	Cost	Value	Recouped	Cost	Value	Cost Recouped	
Bathroom Remodel         68,235         39,102         57.3%         61,196         30,229         49.4%         59,979         35,456           Deck Addition (composite)         45,824         23,607         51.5%         39,993         16,735         41.8%         39,339         22,171           Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691	<u>_</u>									68.4%	
Deck Addition (composite)         45,824         23,607         51.5%         39,993         16,735         41.8%         39,339         22,171           Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691		- ,	·		-	•			· · · · · · · · · · · · · · · · · · ·	57.1%	
Garage Door Replacement         3,403         2,426         71.3%         3,301         2,239         67.8%         3,304         2,810           Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691								,		59.1%	
Grand Entrance (fiberglass)         8,678         6,124         70.6%         8,364         5,029         60.1%         8,358         5,855           Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691	* * * *							1	,	56.4%	
Major Kitchen Remodel         138,922         80,790         58.2%         125,164         75,395         60.2%         122,991         76,149           Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691	<u> </u>		, -			· · · · · · · · · · · · · · · · · · ·		-,		85.0%	
Master Suite Addition         282,498         150,970         53.4%         253,908         123,921         48.8%         250,687         150,140           Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691						· · · · · · · · · · · · · · · · · · ·				70.1%	
Window Replacement (vinyl)         17,096         12,118         70.9%         15,406         9,634         62.5%         15,282         11,286           Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691	<u> </u>	, -	,		-, -	-,		,	-, -	61.9%	
Window Replacement (wood)         20,309         13,934         68.6%         18,920         11,832         62.5%         18,759         13,691					,			,	· · · · · · · · · · · · · · · · · · ·	59.9%	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			, -					-, -	,	73.9%	
CONFIDENCE LEVEL: 95% +/-6.9 CONFIDENCE LEVEL: 95% +/-2.6	Window Replacement (wood)	20,309	13,934	68.6%	18,920	11,832	62.5%	18,759	13,691	73.0%	
					CONFIDENC	E LEVEL: 95% +/-6	5.9	CONFIDENCE L	EVEL: 95% +/-2.	6	

Note: In four markets—Pensacola, Palm Springs, Quad Cities, and West Palm Beach—the job costs are an average of the costs for that project in that particular market's Census Division.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2016 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



The 2017 REMODELING Cost vs. Value Report has been brought to you thanks to the following companies.




















CLUBHOUSEDECKING.COM



# Designed for Decks and the People Who Build Them.

## Simple is Beautiful.

It's simple—open the package, remove the panels, fasten the brackets. Because you already have enough in your life that's complicated.

Visit www.FortressRailing.com to learn more.



844.909.2999

# SO COST EFFECTIVE it practically PAYS FOR ITSELF



Upgrading a garage door is one of the most cost effective renovations your clients can make.


In fact, according to the Cost vs. Value Report, replacing a basic garage door with an upgraded one from Overhead Door returned over 90% on original cost. Now, that's a return on investment you can take to the bank.

The Genuine. The Original.



\* Based on National Association of Realtors members included in Cost vs. Value Study for midrange projects rather than actual sales data. Complete data from the Remodeling 2016 Cost vs. Value report can be downloaded at www.costvsvalue.com.


www.OverheadDoor.com



Visit www.provia.com to find out how you can experience The Professional Way.




Doors | Windows | Siding | Stone



Visit www.provia.com to find out how you can experience The Professional Way.









# Introducing Revive pocket replacement windows

Why choose Windsor's replacement windows? We've got a pocket full of reasons.



### **Trusted Name**

Outstanding quality customers expect from Windsor – in an all-new line of pocket replacement windows.



### **Energy Efficiency**

Replacement windows improve thermal performance, keeping customers comfortable while reducing heating and cooling bills.



### **Easy Installation**

Quick and simple replacement process – often it requires no trim removal – means windows typically install in about an hour.



### **Precise Fit**

Built to exact specifications for a perfect fit, every time.



### **Endless Options**

Three construction materials with multiple glass, grille, hardware, color and finish combinations sure to fit any style.



### **Fast Delivery**

Place your order and receive the windows in three to four weeks.



Visit www.windsorrevive.com to discover even more reasons to choose Revive.

